	Туре	L #	Hits	Search Text	DBs	Time Stamp	e n t s	ErrorDefiniti	Errors
1	BRS	L1	2312	382/141,143-15 3.ccls.	USPAT; US-PGPUB	2004/06/16 07:45			0
2	BRS	L2	918	348/86-92,125, 127.ccls.	USPAT; US-PGPUB	2004/06/16 07:45			0
3	BRS	L3	989	356/237.1,239. 1.ccls.	USPAT; US-PGPUB	2004/06/16 07:45			0
4	BRS	L4	3830	1 2 3	USPAT; US-PGPUB	2004/06/16 07:45			0
5	BRS	L5	167	inspect\$ near composite	USPAT; US-PGPUB	2004/06/16 08:07			0
6	BRS	L6	23	5359525.URPN.	USPAT	2004/06/16 08:03			0

	Туре	L #	Hits	Search Text	DBs	Time	Stamp	ļ-l	ErrorDefiniti	Er ro rs
1	BRS	L1	13095 2	(composite near (structure material))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004, 15:42	/06/15 2			0
2	BRS	L2	229	1 near (inspect\$ detect\$ defect)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004, 15:46	/06/15 5			0
3	BRS	L3	3544	1 same (inspect\$ detect\$ defect)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004, 15:45	/06/15 5			0
4	BRS	L4	2693	1 same (inspect\$ detect\$ defect)	USPAT; US-PGPUB	2004, 15:45	/06/15 5			0
5	BRS	<b>L</b> 5	74	3 and ((two multiple plural\$4) near light)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004, 15:47	/06/15 7			0